

問題内容	発生理由	正しい設定	参照頁
APRSパケットを受信できない	1. グループコードが正しく設定されていない 2. データ長、パリティなどが正しく設定されていない 3. 適切なパケット転送速度が設定されていない	1. Menu 3で、" APK101 "を設定する 2. パケットモードを選択して、次のコマンドをPCから内蔵TNCに送り、その後" APRSモード "を選択する [AW8] [ENTER] [PAR 0] [ENTER] [RESTART] [ENTER] 3. Menu 3で、[1200]bpsを選択する。 (パケット通信速度が1200bpsの場合)	22 41, 47, 48 13
GPS受信機を接続し、Menu 3-Cで" AUTO "を選択しているが、位置情報が発信されない	GPS受信機がまだ位置を補足していない	"AUTO" を選択している場合、TM-D700はGPS受信機から位置情報を受信するまでは位置情報の発信を行わない GPS受信機を接続していない場合は、Menu 3-2で[NOT USED]を選択しなければならない	10
You cannot superimpose information onto the VC-H1 monitor.	You failed to correctly enter information to be superimposed.	Use Menu 2-1 to 2-6 to correctly enter the desired information.	36, 37
You cannot program the VC-H1 with a SSTV mode.	Bad cable connections.	Refer to the instruction manual for the VC-H1 and correctly connect the VC-H1 to the transceiver.	35
You cannot activate Visual Scan, Remote Control (Menu 1-A-3), nor Repeater (Menu 1-7-6).	You selected APRS or Packet mode.	Press [F] (1 s), [TNC] repeatedly so neither " TNC APRS " nor " TNC PKT " is visible.	4, 11